


T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 9 Corner common to sections 3, 4, 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Tree	Distance
<u>Y. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>
<u>18"</u>	<u>24"</u>	<u>24"</u>	<u>18"</u>
<u>N49E</u>	<u>N61W</u>	<u>S46W</u>	<u>S72E</u>
<u>23LKS</u>	<u>56LKS</u>	<u>50LKS</u>	<u>64LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1925 By JOHN GREENE  
Location filed COUNTY RESURVEY PLAT "E-51"  
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1984 By Bill Okerman  
Corner Certificate  
Find 1962 monument lying down w/ cap broken  
off and NW & SE 1962 B.T.S.  
Set 2 1/2" I.P. w/ 3" brass cap

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Bearing Trees	Reference Objects
<u>R. Pine</u>	<u>R. oak</u> <u>R. oak</u> <u>R. oak</u> <u>W. Pine</u>
<u>20"</u>	<u>9"</u> <u>10"</u> <u>16"</u> <u>24"</u>
<u>N41W</u>	<u>N53E</u> <u>S50E</u> <u>S6E</u> <u>S86W</u>
<u>96.70'</u>	<u>66.37'</u> <u>34.21'</u> <u>18.20'</u> <u>57.40'</u>
<u>1962 tie</u>	<u>1962 tie</u>

Subsequent Corner Restoration E 13

Year surveyed 1915 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument CO DITCH SURVEY BK 18 BOX 3  
OF CO. DITCH SURVEY BOOKS, PG 2F

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962  
Certificate - Bill Okerman - 1985  
Doc. # 280558

1977 - W. Curo - Certificate of survey  
indicates monument in place