


Index No. E 19-20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
MC# 44 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

		Bearing Trees	
Species	<u>BIRCH</u>	<u>POPLAR</u>	
Diameter	<u>6"</u>	<u>5"</u>	
Bearing	<u>S78E</u>	<u>N81E</u>	
Distance	<u>27 LKS</u>	<u>68 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument SET 1X36" I.P. w/ BRASS CAP

T141N R31W
MC 52
T511
1917

Evidence of Subsequent Corner Restoration

Year of search 1999 By Landecker & Assoc.
Cert of Survey indicates GLO Monument
in place.

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>POPLAR</u>	
Diameter	<u>7"</u>	<u>8"</u>	
Bearing	<u>N7 1/2 W</u>	<u>S42 1/2 E</u>	
Distance	<u>71 LKS</u>	<u>77 LKS</u>	

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CHRISTMAS POINT
W.J. SPAIN JR 1960

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____