


Index No. E 20-21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
MCH# 43 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>ELM</u>	<u>ELM</u>	
<u>10"</u>	<u>6"</u>	
<u>S43W</u>	<u>N20W</u>	
<u>15LKS</u>	<u>48LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1917 By GLD
Location filed SEC. OF STATE
Monument SET 1X36" IP. W/BRASS CAP
T141N R31W
52/mc
511

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>BIRCH</u>	<u>5"</u>	<u>N50W</u>	<u>22LKS</u>
<u>MOUND OF STONE</u>	<u>2' BASE</u>	<u>1 1/2' HIGH</u>	<u>W. OF COR.</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - CHRISTMAS POINT
W. J. SPAIN JR 1960

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____