


Index No. G 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E14 12 Corner common to sections 12 AND 7-141-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Y. PINE</u>	<u>W. BIRCH</u>	
<u>30"</u>	<u>3"</u>	
<u>N87 1/2 E</u>	<u>S89 W</u>	
<u>7 LKS</u>	<u>12 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO  
Location filed SEC. OF STATE  
Monument SET 1 X 36" I.I.W/BRASS CAP PROPORTIONALLY  
14  
5/2/57  
1917

Evidence of Subsequent Corner Restoration

Year of search 1962 By PETE MEYER  
Found GLO monument laying under road surface; 8" W. Pine N13 1/4 E 169.62' now 14"; 10" Y. Pine S69 1/2 W 374.22' now 24" stump. Set 6" x 24" cylindrical concrete monument capped with 3" stamped bronze tablet.

Species	Bearing	Trees, Reference Objects
<u>W. PINE</u>	<u>Y. PINE</u>	
<u>8"</u>	<u>10"</u>	
<u>N13 1/4 E</u>	<u>S69 1/4 W</u>	
<u>257 LKS</u>	<u>567 LKS</u>	

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>OAK</u>		
<u>9"</u>	<u>5"</u>		
<u>S57 1/2 E</u>	<u>S57 W</u>		
<u>30.5'</u>	<u>16.8'</u>		

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_