


Index No. HJ-17-18

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5th Coordinates: X _____ Y _____

Corner common to sections _____
Reference to Resurveyation Corner in Leach Lake



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument 6" Sq. wood post
in marsh - southern extremity of Leach Lake

Species	Bearing	Trees
<u>Tam</u>	<u>N 1/2 E</u>	<u>Nil</u>
<u>8"</u>	<u>10"</u>	
<u>553E</u>	<u>587E</u>	
<u>172 LKS</u>	<u>650 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985 By Gary Sturison
Corner Certificate - Doc # 284981

Find possible Pine stump B.T.
set 2" sq. mon. w/ aluminum cap - survey marker sign
corner 215.10' ESE of computed position for corner

Bearing	Distance	Reference Objects
<u>Balsam</u>	<u>11"</u>	<u>N30E</u>
<u>Spruce</u>	<u>13"</u>	<u>26.54'</u>
<u>Spruce</u>	<u>9"</u>	<u>525W</u>
<u>Mile Post 21</u>	<u>19.20'</u>	<u>165W</u>
	<u>5.50'</u>	<u>2184.0'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____