


Index No. J 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument 12" J. PINE

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	J. PINE	J. PINE	J. PINE	J. PINE
Diameter	<u>7"</u>	<u>10"</u>	<u>12"</u>	<u>10"</u>
Bearing	<u>N23E</u>	<u>N17W</u>	<u>S48E</u>	<u>S50W</u>
Distance	<u>23 LKS</u>	<u>43 LKS</u>	<u>25 LKS</u>	<u>21 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1984 By Bill Okerman
Location filed Corner Certificate
Monument Replaced 1 1/2" i.p. Fnd in 1962, 1965 & 1980
also 1980 trees replaced, van w/ 2 1/2" i.p. w/ 3" brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	J. Pine	J. Pine	Birch	Steel posts
Diameter	<u>12"</u>	<u>10"</u>	<u>8"</u>	<u>8' long</u>
Bearing	<u>S3W</u>	<u>N52E</u>	<u>N19E</u>	<u>N54W North S36E</u>
Distance	<u>5.96'</u>	<u>17.48'</u>	<u>32.95'</u>	<u>5.85' 3.27' 9.09'</u>

← 1980 trees

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Bill Okerman - 1985
Doc. # 280571

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____