


Index No. JR1

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>Poplar</u>	<u>SPRUCE</u>	<u>W. PINE</u>
Diameter	<u>6"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>N45E</u>	<u>N35W</u>	<u>S29E</u>
Distance	<u>9 LKS</u>	<u>10 LKS</u>	<u>28 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1917 By GLO  
 Location filed SEC. OF STATE  
 Monument FIND NE, SW & SE CORNERS  
SET 2x36" I.P. W/BRASS CAP T14IN R31W  
511 512  
514 513

Evidence of Subsequent Corner Restoration

Year of search 1962 By PETE MEYER  
 Found GLO monument in good condition;  
7" N. Pine N53 1/2 E 123.42' now 14"; stump  
S8W 13.86'; stump S29E 18.48'.

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>CEDAR</u>	<u>ROUND OF STONE</u>
Diameter	<u>7"</u>	<u>12"</u>	<u>2' BASE</u>
Bearing	<u>N53 1/2 E</u>	<u>S31 1/2 E</u>	<u>1 1/2' HIGH</u>
Distance	<u>187 LKS</u>	<u>205 LKS</u>	<u>W. OF COR.</u>

Bearing Trees, Reference Objects

<u>OAK</u>	<u>OAK</u>	<u>Cedar Post</u>	<u>Cedar Post</u>
<u>6"</u>	<u>10"</u>	<u>4x4x 72"</u>	<u>4x4x 72"</u>
<u>S32 1/2 W</u>	<u>N 7 1/2 E</u>	<u>S57 E</u>	<u>N57 W</u>
<u>27.0'</u>	<u>38.0'</u>	<u>3.0'</u>	<u>3.0'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_