


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
MC # 16 Corner common to sections 24, 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST
Location filed COUNTY RESURVEY PLAT "E-53"
Monument IRON MONUMENT
1920, E.B. HORST, BOOK "C" P. 459 FWD CORNER SET FROM
U.S. B.T.S. SET 2x48" I.M. (P. 460)
- a. 150 on microf. film-roll 115 BK 80 P. 96, 98

Bearing Trees, Reference Objects

Species N. PINE N. PINE
Diameter 9" 8"
Bearing N23-34W S46-03E
Distance 10.5' 4.0'
1920 TICS

Evidence of Subsequent Corner Restoration

Year of search 1917 By John Green
microfilm-roll 115 BK 80 P. 58-59
End M.C.

Bearing Trees, Reference Objects

N. Pine
10"
N27-15W
10.75'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962
Found 8" N. Pine S46E 4.0' now 13";
9" N. Pine N23W 10.5' now 15". Set
2" x 5' galvanized wrought iron pipe
filled with concrete and capped with 3"
stamped bronze tablet. Rock 3x4x2'
S62E 28.0'.