


Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
N. 1430 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees

Species Birch STD
Diameter 8"
Bearing N70W
Distance 209 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. Horst
Location filed COUNTY RESURVEY PLAT "E-54"
Monument IRON MONUMENT
1921, E. B. Horst, Book "C" P456 SET BY 40" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1984 By Tony Kerick
Corner Certificate
Find 3" brass cap from 1958 by Harold Curo

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

	<u>Ash</u>	<u>Elm</u>	
<u>S.W. Corner</u>			<u>N.W. Corner</u>
<u>shed foundation</u>	<u>7"</u>	<u>8"</u>	<u>Garage</u>
<u>N13W</u>	<u>N38W</u>	<u>566-21W</u>	<u>553W</u>
<u>60.37'</u>	<u>21.40'</u>	<u>31.45'</u>	<u>31.32'</u>
<u>SE Cor. Garage</u>	<u>S8E</u>	<u>33.39'</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SHADY LAKE
HAROLD Curo 1955
CERTIFICATE - PETE MEYER - 1958
Certificate - Tony Kerick - 1984
Doc. # 280484

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____