


Index No. T 13

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 28 Corner common to sections 27, 28



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Species	Bearing	Trees
<u>W. PINE</u>	<u>BIRCH</u>	
<u>6"</u>	<u>6"</u>	
<u>N6W</u>	<u>S70E</u>	
<u>7 LKS</u>	<u>12 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1961 By PETER MEYER
 Location filed COUNTY RESURVEY PLAT E-59'
 Monument IRON MONUMENT - SET PROPORTIONALLY SET TIES

Species	Bearing	Trees, Reference Objects
<u>R. PINE</u>	<u>OAK</u>	<u>OAK</u>
<u>18"</u>	<u>6"</u>	<u>9"</u>
<u>S44W</u>	<u>N60W</u>	<u>S75E</u>
<u>69.9'</u>	<u>6.1'</u>	<u>45.8'</u>

Evidence of Subsequent Corner Restoration
 Year of search 1988 By Walt Curo
 Corner Certificate - Doc # 302619

Find 1961 monument - set 2' x 5' I.P. w/ brass cap 76.36' S. (at true proportion)

Bearing	Trees, Reference Objects	1961
<u>Burr oak</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>8"</u>	<u>14"</u>	<u>15"</u>
<u>S 59 E</u>	<u>S 19 W</u>	<u>N 81 W</u>
<u>69.40'</u>	<u>46.10'</u>	<u>44.56'</u>
		<u>Monument North 76.36'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - Peter Meyer - 1961
Certificate - Walt Curo - 1988

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____