


T. 141 R. 31 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 27 Corner common to sections 26, 27



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species BIRCH J. PINE STUB  
 Diameter 5" 8"  
 Bearing S 70 E N 71 W  
 Distance 14 LKS 17 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1922 By E. B. HORST  
 Location filed COUNTY RESURVEY PLAT "E-53"  
 Monument 2x40" IRON MONUMENT  
1921, BOOK "C", E. B. HORST, SET CORNER 2x40" I.M.

Evidence of Subsequent Corner Restoration  
 Year of search 1987 By Walt Curo  
Corner Certificate - Doc # 302145  
Find 2 3/4" capped I.P. and 2 1959 trees

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  

<u>Burr oak</u>	<u>Red oak</u>	<u>Red oak</u>	<u>Red oak</u>
<u>12"</u>	<u>8" (Dead)</u>	<u>8"</u>	<u>10"</u>
<u>N 3 E</u>	<u>N 39 E</u>	<u>S 53 W</u>	<u>N 85 W</u>
<u>39.60'</u>	<u>10.70'</u>	<u>34.89'</u>	<u>34.40'</u>

↖ old BT's ↗

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - HAROLD Curo - 1959  
Certificate - Walt Curo - 1987