


Index No. T 2-3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections _____
ON E-W 1/4 LINE ON W-SIDE HOWARD LAKE



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____
 Original monument _____

Year of search _____ By _____
 Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1959 By Harold Curo
 Location filed _____
 Monument Set 2 3/4 x 60" capped monument filled with concrete.

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species Cedar Post Cedar Post
 Diameter 4x4x100" 4x4x100"
 Bearing N18°37'W S13°31'W
 Distance 18.60' 16.80'

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1959

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____