


Index No. V 20-21

CASS COUNTY LAND CORNER RECORD



141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
 MC # 8 Corner common to sections 26, 35

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument POST

Bearing Trees  
 Species BIRCH BIRCH  
 Diameter 7" 0"  
 Bearing S59W N34E  
 Distance 1245 1665

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1922 By E. B. HORST  
 Location filed COUNTY RESURVEY PLAT "E-53"  
 Monument 2x48" I.M. W.C.M.C. 20' W.  
1928, E.B. HORST - COUNTY RESURVEY PLAT "E-55" I.M.  
1920, E.B. HORST, BOOK "C" P 463 SET W.C.M.C.  
P. 467 SET 2x48" I.M. - also on microfilm  
roll 115 BK 80 P. 113

Bearing Trees, Reference Objects  
 Species BASSWOOD W. OAK  
 Diameter 12" 14"  
 Bearing N21-45W S41-15W  
 Distance 24.0' 13.6'  
1920 ties

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - PARK POINT  
JOHN W. CURS 1947  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_