


Index No. V3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 31 Corner common to sections 30,31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>BIRCH</u>	<u>OAK</u>	_____	_____
Diameter	<u>5"</u>	<u>7"</u>	_____	_____
Bearing	<u>N7E</u>	<u>S19W</u>	_____	_____
Distance	<u>1945</u>	<u>2345</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST  
Location filed COUNTY RESURVEY PLAT "E-54, E-55"  
Monument IRON MONUMENT  
1921, E.B. HORST, COUNTY BOOK "C" P452 SET CORNER.  
P. 456 SET 2x4" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1984 By Tony Kerick  
Corner certificate -  
Found 3" brass cap set in 1959 by Harold Curo

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Ash stump</u>	<u>Tam.</u>	<u>Ash</u>	<u>Tam.</u>
<u>10" scribed</u>	<u>7"</u>	<u>7" 12" row</u>	<u>4" row 8"</u>
<u>N46W</u>	<u>N53W</u>	<u>N70E</u>	<u>S31E</u>
<u>109.9'</u>	<u>45.15'</u>	<u>46.65'</u>	<u>70.35'</u>
<u>1959 B.T.</u>		<u>1959 t.c</u>	<u>1959 t.c</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - HAROLD Curo - 1959  
Certificate - Tony Kerick - 1984  
Doc. # 280489

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_