


Index No. X 1-2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 57A Coordinates: X _____ Y _____

SMC Corner common to sections
ONE-W 1/4 LINE W. SIDE LAKE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1959 By Harold Curo
Location filed _____
Monument Set 2 3/4 x 60" capped monument filled with concrete.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Elm Elm W. Pine
Diameter 14" 6" 14"
Bearing S63°36'W S84°33'W South
Distance 45.75' 46.50' 59.14'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1959

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____