Index No. 43

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

C.S. 11/6 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found 1 3/4" iron pipe Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Red Pine	Boulder		
Diameter	23"	5x4x3'		
Bearing	S20E	North		
Distance	80.5'	0.2'		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____