


Index No. 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5th Coordinates: X _____ Y _____

W 1/4 Corner common to sections 31
(STANDARD)



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____
Monument Found 1 3/4" iron pipe set 2"x5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species W. Pine OAK
Diameter 24" 6"
Bearing N11 1/2 W N60 E
Distance 72.4' 31.1'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Sept. 2000 - CC&O
Find in place 2" OD IP, up 1.7' on SW side of USFS Brass Cap Mon, up 1.8' w/oven wire fence 16' E of Mon.

Ref. Trees
24" W. Pine N11°W 72.40' (exist. nail)
5" Spruce N72°W 11.46' (1984 tie)
4" Spruce N88°W 1.82' (exist. nail)
8" Spruce S16°E 36.06
4" Spruce N60°E 6.77' (exist. nail)
6" W. Oak N60°E 31.10' (exist. nail)
