


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
51432 Corner common to sections 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	W. Birch	W. Birch	
Diameter	<u>6</u>	<u>6</u>	
Bearing	<u>N31W</u>	<u>N42E</u>	
Distance	<u>9 lks</u>	<u>10 lks</u>	

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1984 By Tony Kerick
 Location filed Corner Certificate
 Monument End 2" iron, John Curo had set a 2" iron at this corner from evidence he found about 1910. Accept found 2" iron as corner set 3" brass cap monument in place of 2" iron - set 2" iron North & alongside new monument

Bearing Trees, Reference Objects

Species	Elm	W.oak	R.oak
Diameter	<u>6"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>N68W</u>	<u>N10W</u>	<u>N53E</u>
Distance	<u>28.37'</u>	<u>29.53'</u>	<u>17.24'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Tony Kerick - 1984
Doc. # 280500