


Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument Post

Species	Bearing	Trees	Distance
<u>W. Pine</u>	<u>BIRCH</u>	<u>BIRCH</u>	<u>N. Pine</u>
<u>48"</u>	<u>8"</u>	<u>8"</u>	<u>36"</u>
<u>N35E</u>	<u>S36W</u>	<u>N66W</u>	<u>S35E</u>
<u>14LKS</u>	<u>120LKS</u>	<u>73LKS</u>	<u>95LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1985 By Roger Mustonen

Location filed Corner Certificate - Doc # 286238

Monument End remnants of w. pine stump 54"  
S35W 14 LKS and st. 16" below surface of 4-5"  
dia. hole find post point - set 2" sq steel monument  
w/ stamped aluminum cap

Species	Bearing	Trees, Reference Objects	Distance
<u>J. Pine</u>	<u>N. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>
<u>8"</u>	<u>25"</u>	<u>11"</u>	<u>9"</u>
<u>N66E</u>	<u>S19E</u>	<u>S75W</u>	<u>N11W</u>
<u>16.35'</u>	<u>29.32'</u>	<u>14.30'</u>	<u>25.64'</u>

Sign post 1' west

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Roger Mustonen - 1985

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_