


T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 29 Corner common to sections 28, 29



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1871
 Original monument POST

Bearing Trees
 Species CEGAR PAM
 Diameter 10" 14"
 Bearing S39W N33E
 Distance 18 LKS 22 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1985 By Roger Mustbren
 Location filed Corner Certificate - Doc # 286241
 Monument Find remnants of 15" down cedar tree and find tie south 13 chains to brook to fit with 6LO call

Bearing Trees, Reference Objects
 Species Ash Ash Ash sign post
 Diameter 8" 4" 5"
 Bearing S35W N55W East South
 Distance 18.32' 8.14' 2.60' 0.77'

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Roger Mustbren - 1985