Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____

N1/4 4 Corner common to sections 4 AND 33 - 143 - 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	FIR.	W. PINE		
Diameter	10"	18"		
Bearing	S23E	N31E		
Distance	13 LKS	19 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1916 By _____

Location filed _____

Monument CO DITCH SURVEY BK 7 BOX 2 OF CO. DITCH SURVEY BOOKS, PG 54

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM. OSUPSEN

FND 1½" IRON PIPE SET IN 1916

ADD ALUM. CAP TO EXISTING PIPE

SET 8' STEEL SIGN POSTS 3.8 WEST, 5.0 EAST

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

	BALM OF GILEAD	BALM OF GILEAD	BALM OF GILEAD	
	12	3	10"	
	N 84 W	N 8 W	N 8 E	
	40.43	40.96	37.32	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERT. BY WM. OSUPSEN 1990

Doc. # 335161

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____