


T. 142 R. 26 M. 574 Coordinates: X _____ Y _____
MC# 21 Corner common to sections 2, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Bearing Trees	
Species <u>TAM</u>	<u>TAM</u>
Diameter <u>4"</u>	<u>4"</u>
Bearing <u>NBE</u>	<u>S28W</u>
Distance <u>20LKS</u>	<u>13 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997 By Laverne Levelling

Set alum. rod w/ stamped alum. cap for witness to prop. meander corner position, measured between section corner common to Sec. 2, 3, 10, & 11, & a theoretical south qtr. corner of Sec 2, on West shore of NGhton Lake.

Cert. filed: June 1, 1998; Doc. # 400503

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Spruce</u>	<u>Aspen</u>	<u>Tamarack</u>
<u>1.100m</u>	<u>0.130m</u>	<u>0.150m</u>
<u>N38°W</u>	<u>N89W</u>	<u>S29W</u>
<u>4.830m</u>	<u>20.536m</u>	<u>6.440m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____