


T. 142 R. 26 M. 574 Coordinates: X _____ Y _____
MC# 24 Corner common to sections 2, 11



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees
<u>TAM.</u>	<u>TAM.</u>	
<u>6"</u>	<u>6"</u>	
<u>N32E</u>	<u>S87E</u>	
<u>20ks</u>	<u>35ks</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1997 By Laverne Leuelling
Monumented a witness of the meander corner,
determined by proportionate measurement, on
line between SW corner of Sec. 2 and theoretical
South ctr. corner of Sec. 2.
Cert. Filed: June 1, 1998; Doc. 400500

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Ash</u>	<u>0.130m</u>	<u>N26W</u>	<u>12.538 m</u>
<u>Elm</u>	<u>0.134m</u>	<u>S26E</u>	<u>1.486m</u>
<u>Ash</u>	<u>0.165m</u>	<u>N6E</u>	<u>7.280m</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____