


Index No. ERI

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>SUGAR</u>	<u>FIR</u>	<u>BIRCH</u>	<u>ASPEN</u>
Diameter <u>10"</u>	<u>6"</u>	<u>14"</u>	<u>16"</u>
Bearing <u>N54W</u>	<u>S53E</u>	<u>S77W</u>	<u>N41E</u>
Distance <u>17 LKS</u>	<u>13 LKS</u>	<u>30 LKS</u>	<u>22 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997 By Laverne Leveling
Monumented section corner position arrived at
by single proportioning between section corner
common to Sec. 1, 2, 35 & 36, T. 142, R. 26 & the
section corner common to Sec. 11, 12, 13, & 14.
Cert. Filed: June 1, 1998; Doc. 400499

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Steel Signpost	Steel Signpost	Steel Signpost	Steel Signpost
<u>N45W</u>	<u>S47W</u>	<u>S44E</u>	<u>N43E</u>
<u>1.412m</u>	<u>0.980m</u>	<u>1.200m</u>	<u>2.042m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____