


T. 142 R. 26 M. 574 Coordinates: X _____ Y _____
N148 Corner common to sections 5,8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Bearing Trees

Species	Bearing	Distance
<u>Aspen</u>	<u>BIRCH</u>	
<u>6"</u>	<u>4"</u>	
<u>57E</u>	<u>N31E</u>	
<u>13 LKS</u>	<u>10 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By JAMES FLYNN

Location filed COUNTY BOOK "C" P. 387

Monument END OLD GOVT. B.T.: SET 4" BIRCH N31E 10 LKS SET 1 1/2 x 44" IRON MONUMENT COUNTY RESURVEY 1920 "E-2"

Evidence of Subsequent Corner Restoration

Year of search 1964 By William Okerman

Found 2" iron pipe. Set 2"x60" galvanized steel monument capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Aspen</u>	<u>N3W</u>	<u>50'</u>
<u>4"</u>		

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Oak</u>	<u>562W</u>	<u>46.5'</u>
<u>Maple</u>	<u>528E</u>	<u>56.2'</u>
<u>Oak</u>	<u>N89E</u>	<u>64.4'</u>
<u>Cedar Post</u>	<u>South</u>	<u>2.0'</u>
<u>6"</u>		
<u>6"</u>		
<u>6"</u>		

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - OKERMAN 1964