Index No. J 3

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____

N1/4 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Bearing Trees

Species	SPRUCE	SPRUCE		
Diameter	6"	5"		
Bearing	N12E	S81E		
Distance	5 LKS	7 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1916 By _____

Location filed _____

Monument Co DITCH SURVEY BK 7 BOX 2 of Co DITCH SURVEY BOOKS, PG 49

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1963 By W. Okerman

Search made after testimony of resident that corner fell just south of original roadway. All evidence apparently destroyed by road upgrade

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____