


Index No. N 18-19

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C. # 17 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument M.C. Post

Species	Bearing	Trees
<u>SPRUCE</u>	<u>SPRUCE</u>	
Diameter <u>4"</u>	<u>6"</u>	
Bearing <u>N25E</u>	<u>S69E</u>	
Distance <u>945</u>	<u>545</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1997, June By Laverne Leuelling

Placed alum. rod at position of U.S.D.A. - F.S. concrete mon.

Cert. Filed: Dec 8, 1997; Doc. #395062

Cert. Filed: June 1, 1998; Doc. #400493

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Cedar</u>	<u>0.457m</u>	<u>N50E</u>	<u>33.589m</u>
<u>Cedar</u>	<u>0.269m</u>	<u>S63E</u>	<u>35.339m</u>
<u>Ash</u>	<u>0.198m</u>	<u>N63E</u>	<u>9.906m</u>
<u>St. Signpost</u>	<u>E</u>		<u>1.000m</u>

Subsequent Corner Restoration N-18-19

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERTIFICATE - OKERMAN 1963

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_