


Index No. P21

CASS COUNTY LAND CORNER RECORD

T. 14 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 23 Corner common to sections 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Species	Bearing	Tree	Distance
<u>W. PINE</u>	<u>W. PINE</u>		
<u>30"</u>	<u>30"</u>		
<u>S 58 E</u>	<u>S 46 W</u>		
<u>18 LKS</u>	<u>16 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1963 By William Okerman
Location filed _____
Monument Found 1 1/2" iron pipe. Set 2"x60" galvanized steel pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search 1997, June By Lavene Leuelling
Found, accepted, & maintained 1963 U.S.D.A. - E.S. monument.

Cert. Filed: Dec 8, 1997; Doc. #395069

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>11"</u>	<u>N 76 E</u>	<u>9.9'</u>
<u>Oak</u>	<u>10"</u>	<u>S 48 W</u>	<u>77.7'</u>
<u>Cedar Post</u>	<u>4x4x60"</u>	<u>West</u>	<u>3.0'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Red Oak</u>	<u>0.310m</u>	<u>N 76 E</u>	<u>3.020m</u>
<u>Casswood</u>	<u>0.500m</u>	<u>S 40 E</u>	<u>19.616m</u>
<u>Red Oak</u>	<u>0.380m</u>	<u>S 44 W</u>	<u>23.670m</u>
<u>St. Signpost</u>		<u>W</u>	<u>1.000m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____