


Index No. P 25

CASS COUNTY LAND-CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X Y
E 74 24 Corner common to sections 24 and 19-142-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>OAK</u>	<u>OAK</u>	_____	_____
Diameter	<u>8"</u>	<u>6"</u>	_____	_____
Bearing	<u>S 84 W</u>	<u>N 51 E</u>	_____	_____
Distance	<u>37 LKS</u>	<u>28 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997, June By Laverne Leuelling
Set corner midway and on line between the
theoretical NE corner of Sec 24 & the SE
corner of same section.

Cert Filed: Dec. 8, 1997; Doc. #395070

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Aspen</u>	<u>Ash</u>	<u>Aspen</u>	<u>St. Signpost</u>
<u>0.208m</u>	<u>0.158m</u>	<u>0.163m</u>	_____
<u>N 50 E</u>	<u>N 74 W</u>	<u>N 52 W</u>	<u>N</u>
<u>1.640m</u>	<u>8.520m</u>	<u>7.662m</u>	<u>0.590m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____