


Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Bearing Trees

Species	<u>Tam</u>	<u>Tam.</u>	_____
Diameter	<u>8"</u>	<u>10"</u>	_____
Bearing	<u>S2E</u>	<u>S3W</u>	_____
Distance	<u>326 LKs</u>	<u>331 LKs</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By _____
Location filed _____
Monument Co DITCH SURVEY BOOK 6 BOX 2
Co DITCH SURVEY BOOKS, PG 18

Evidence of Subsequent Corner Restoration

Year of search 1963 By William Okerman
Found 4"x4" Cedar post. Set 2" galvanized steel monument filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Rock</u>	<u>Cedar Post</u>
<u>8"</u>	<u>4"x3'x1'</u>	<u>4x4x60"</u>
<u>S60W</u>	<u>West</u>	<u>East</u>
<u>274.0'</u>	<u>115.9'</u>	<u>2.1'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____