


Index No. T 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	
<u>6"</u>	<u>12"</u>	
<u>S40E</u>	<u>N6W</u>	
<u>42 LKS</u>	<u>37 LKS</u>	

Species	Diameter	Bearing	Distance
Original Bearing Trees Found			
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By JAMES FLYNN
Location filed COUNTY BOOK "C" P. 415
Monument END IRON MONUMENT
1912, JAMES FLYNN BOOK "B" P. 514-515 END
OLD GOVT B.T. : 12" BIRCH (DOWN) N6W 37 LKS.
SET POST COUNTY RESURVEY 1921 "E-2" I.M.

Evidence of Subsequent Corner Restoration

Year of search 8/2000 By CCSO
Corner destroyed by road const.
Set Alum. cap tel spar at calc.
position, 36'± E. of new & CR #52
and 9'± N. of road to east.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

W. Pine	R. Oak	Ash	N. Pine
<u>9"</u>	<u>14"</u>	<u>4"</u>	<u>8"</u>
<u>N88°W</u>	<u>N17°E</u>	<u>S53°E</u>	<u>S45°W</u>
<u>116.60'*</u>	<u>70.15'*</u>	<u>65.27'*</u>	<u>104.46'*</u>

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____