


Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 114 2 Corner common to sections 2 AND 35-143-27



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1873  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species SPRUCE SPRUCE  
Diameter 8" 7"  
Bearing S52E N62W  
Distance 22 LKS 15 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1998 By NKSEM DLS #16089  
Set a 1/2" x 6' aluminum rod w/alum. cap  
9" above ground

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
Ash Ash Aspen Steel  
8" 5" 6" Sign Post  
N27°E S86°E S83°W N80°W  
62.39' 6.44' 4.17' 1.37'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at CCRO Dec. #413182

By NKSEM  
Date 5/25/99