


Index No. A23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
N141 Corner common to sections LAND 36-142-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ASPEN FIR
Diameter 14" 6"
Bearing N33W S46E
Distance 8 LKS 10 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1998 By NLSM RLS #16089
Location filed USFS Cass Lake & CCSO
Monument 2" x 48" galv. steel pipe w/ brass cap, 160'± from edge of swamp

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Maple Oak Spruce Steel
Diameter 7" 7" 5" Sign Post
Bearing S20°W N54°W East N86°E
Distance 7.92' 3.69' 34.63' 3.68'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at CCRO Dec #413180

By NLSM
Date 5/25/99