


Index No. A 5-6

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
W-W 1/64 Corner common to sections 5 AND 32-142-27
AP # 1 TR 1551



EXISTING SURVEYS

Original Government Survey

Year surveyed 1920 532
Original monument 1x36" LP. w/ BRASS CAP API TR 1551 55 1920
Bearing Trees
Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____
Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____
Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 4-99 By J. FOSTER
0.400m Cedar 582°W 4.134m to 20d nail in E. face UP 0.610m (Scribe visible)
Steel signpost W 0.846m
0.250m Cedar N60°W 9.524m to 20d nail in S face up 0.170m (No scribe visible)
0.160m Cedar N38°W 1.538m to 20d nail in NE face up 0.440m (Scribed 532.67)
ANGLE POINT #1 Allotment 1551 CAPPED
IRON POST UP 0.230m
0.360m Cedar 533°W 11.796m to 20d nail in NE face up 0.800m (Scribe visible) CERTIFIED 5/5/99 DOC. NO. 412423
LOCATION

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____