


Index No. A 6-7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
MC # 13 Corner common to sections 5 AND 32-143-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>CEDAR</u>	<u>CEDAR</u>
Diameter <u>7"</u>	<u>10"</u>
Bearing <u>N84W</u>	<u>S89W</u>
Distance <u>197 LKS</u>	<u>207 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1920 By GLD
Location filed SEC. OF STATE
Monument END NW. C.T. SET W.C.M.C. 1/36" I.P.
W/BRASS CAP
7143N WC
R27W
532 MC

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLS&M RLS #16089
Set a 1/2" x 15' aluminum rod w/alum. cap

Bearing Trees, Reference Objects	
Species <u>DEAD CEDAR</u>	<u>DEAD CEDAR</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>S75 1/2 W</u>	<u>N88 1/4 W</u>
Distance <u>180 LKS</u>	<u>235 LKS</u>

Bearing Trees, Reference Objects		
<u>Steel</u>	<u>Steel</u>	<u>Steel</u>
<u>Sign Post</u>	<u>Sign Post</u>	<u>Sign Post</u>
<u>East</u>	<u>South</u>	<u>West</u>
<u>2.04'</u>	<u>1.97'</u>	<u>2.08'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at CCRO Doc. # 413584

By NLS&M
Date 6/8/99