



T. 142 R. 27 M. 514 Coordinates: X _____ Y _____
M.C. # 43 Corner common to sections 5 AND 32-143-27

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species T.A.M.
Diameter 6"
Bearing N12E
Distance 750 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1999 By NLS&M RLS #16089
Location filed USFS Cass Lake & CCSO
Monument Aluminum Rod w/ Alum. Cap as witness.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects			
Species	<u>steel</u>	<u>Steel</u>	<u>Steel</u>
Diameter	<u>Sign Post</u>	<u>Sign Post</u>	<u>Sign Post</u>
Bearing	<u>North</u>	<u>East</u>	<u>South</u>
Distance	<u>3.0'</u>	<u>3.0'</u>	<u>3.0'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

