


Index No. G 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. R7 M. 5TH Coordinates: X _____ Y _____
E114 B Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO B.T.
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SEC. OF STATE
Monument SET 8' CEDAR POST 6" SQUARE
4" IN GROUND
MARKED: '14 58 ON W. SIDE
59 ON E. SIDE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____