


Index No. L7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C14 Corner common to sections 17



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1919  
Original monument 1x36" I.P.W. BRASS CAP C14 517 1919

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar Poplar \_\_\_\_\_  
Diameter 6" 6" \_\_\_\_\_  
Bearing S56°4E N52°4W \_\_\_\_\_  
Distance 47 LKS 31 LKS \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_