


Index No. L 9-10

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections 16

E-W 1/4 LINE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1920
 Original monument 1x36" W.P. W/BASSES 5/c SMC
CA 16
1920

Year of search _____ By _____
 Monument found _____

Bearing Trees

Original Bearing Trees Found

Species	Bearing	Distance
<u>PLANE</u>	<u>W 1/4</u>	<u>136 LKS</u>
<u>W. OAK</u>	<u>6"</u>	<u>83 LKS</u>
Diameter		
Bearing	<u>523 3/4 W</u>	<u>N 63 1/4 W</u>
Distance		

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1979 By Gary Stevenson
 Location filed _____
 Monument Found GLO monument in good condition.

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Pine</u>	<u>N 35 W</u>	<u>131.0'</u>
<u>W. Oak</u>	<u>N 65 W</u>	<u>54.8'</u>
<u>Ash</u>	<u>547 W</u>	<u>59.7'</u>
Diameter		
Bearing		
Distance		

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264924

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____