


Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trass		
Species	<u>POPLAR</u>	<u>BIRCH</u>	<u>MAPLE</u>	<u>FIR</u>
Diameter	<u>18"</u>	<u>6"</u>	<u>7"</u>	<u>4"</u>
Bearing	<u>N71W</u>	<u>S50W</u>	<u>S63E</u>	<u>N32E</u>
Distance	<u>14 LKS</u>	<u>7 LKS</u>	<u>29 LKS</u>	<u>17 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD
Location filed SEC. OF STATE
Monument NO ORIG. EVIDENCE SET 2X36" I.P.W/BRASS
CAP. T142N / R27W
S18 / S17
S19 / S20

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	<u>MAPLE</u>	<u>ELM</u>
Diameter	<u>6"</u>	<u>14"</u>	<u>18"</u>	<u>22"</u>
Bearing	<u>N28 1/4 E</u>	<u>S63 1/4 E</u>	<u>S7 1/2 W</u>	<u>N48 W</u>
Distance	<u>33 LKS</u>	<u>21 LKS</u>	<u>52 LKS</u>	<u>70 LKS</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BIG BOY ACRES
W. J. SPAIN JR 1974

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____