


T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
E 14 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BIRCH</u>	<u>PERP</u>	<u>PERP</u>
<u>5"</u>	<u>4"</u>	
<u>S80W</u>	<u>S83E</u>	
<u>234ks</u>	<u>33 kcs</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By J.H. FLYNN
Location filed COUNTY BOOK B P 594-595
Monument BITS CORNER

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
FIND DELAYED WOOD STAKE IN CENTER OF R/O/W
NORTH & ALONGSIDE STAKE - SET 1X36" I.P. W/ BRASS CAP
14
529/528
1919

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>ASPEN</u>	<u>ASPEN</u>	
<u>9"</u>	<u>10"</u>	
<u>S62-30W</u>	<u>S87-20E</u>	
<u>42'</u>	<u>36.4'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>R.OAK</u>	<u>R.OAK</u>	
<u>6"</u>	<u>14"</u>	
<u>N62 3/4 E</u>	<u>S 34 1/2 W</u>	
<u>65 kcs</u>	<u>128 kcs</u>	

Subsequent Corner Restoration

Year surveyed 1983 April By Freeman-Hammitzsch
Location filed Survey Tech - Forester
Monument Found pipe - cap knock off - pipe bent.
Spike set over pipe.
put CC land dept fa, on west B.T.

R. oak - Twin 7.11" S51W 42.3'
R.oak 6" west 38.4'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Roger Mustonen
Doc. # 289503
Found 1" bent iron pipe, partially filled
with concrete; a 60d spike and a 3/4" x
3/6" rebar. Set cast iron monument.
8" Ash N86W 31.81'; 10" Red Oak S46W
42.08'; 6" Red Oak S73E 42.00'

June 2005 T. Freeman #21367
Cert of Survey shows monument found