


142 R. 27 M. 5TH Coordinates: X _____ Y _____
N 1/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument 4" SPRUCE TREE

Bearing Trees
 Species NORWAY POPULAR
 Diameter 5" 6"
 Bearing S45E N40E
 Distance 345 445

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1981 By GARY STEVENSON
 Location filed PLAT OF SURVEY "E-74"
 Monument REPLACED 1/2 x 40" IRON PIPE WITH 2" x 60" GALV. I.P. W/ 3" BRASS CAP

Evidence of Subsequent Corner Restoration
 Year of search 1922 By J.H. FLYNN
COUNTY BOOK D P. 108 END N. PINE 8.T STUMP - IT IS NE - NOT SE. SET POST

Bearing Trees, Reference Objects
 Species BALSAM BIRCH SPRUCE
 Diameter 18" 10" 12"
 Bearing N42W N5E S44W
 Distance 90.87' 15.45' 44.87'

Bearing Trees, Reference Objects
N. PINE STAMP N. PINE
7" 16"
S70E N45E
12' 2'

V-19

Subsequent Corner Restoration
 Year surveyed 9/99 By CCSO
 Location filed #99046
 Monument Found & Located 1981 Brass cap.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260592