


T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35 - 143-28



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>ASH</u>	<u>IRONWOOD</u>	<u>ASH</u>	<u>SPRUCE</u>
Diameter	<u>12"</u>	<u>6"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>N 20 E</u>	<u>N 45 W</u>	<u>S 45 E</u>	<u>S 35 W</u>
Distance	<u>8 LKS</u>	<u>20 LKS</u>	<u>18 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK B "P 220-242"
Monument FIND OLD CUT BIT; STUMP 8" ASH 57SE
18 LKS SET IRON

Evidence of Subsequent Corner Restoration

Year of search 1928 By GLO
FIND 2x36" I.P. W/ BRASS CAP SET IN 1920 BY
HARRINGTON FROM ORIG. BIT. EVIDENCE
ALSO FIND GALV. I.P. BY COUNTY SURVEYOR T143N R28W

also on microfilm - roll 115 BK 77 P. 13, P. 41
set J.M.

534 | 535
53 | 52

	Bearing Trees, Reference Objects	
Species	<u>ELM</u>	<u>BASSWOOD</u>
Diameter	<u>24"</u>	<u>10"</u>
Bearing	<u>S 50 W</u>	<u>N 11 E</u>
Distance	<u>42.60'</u>	<u>39.30'</u>

Bearing Trees, Reference Objects
NO BITS. T142 N
1920

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1982
Doc # 264929
Found 2"x46" galvanized iron pipe. Set
2"x36" iron pipe with 3" brass cap.
6" Ash N11W 65.35'; 5" Ash N33E 54.95';
4" Ash S38E 117.90'; 4" W. Oak 549 W
116.40'.

Dec. 1933, Twp rd order shows no survey