Index No. C 25

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____

E 1/4 1 Corner common to sections 1 AND 6 - 142-27




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument POST

**Bearing Trees**

| | | | | |
|---|---|---|---|---|
| Species | CEDAR | CEDAR | | |
| Diameter | 5" | 8" | | |
| Bearing | S40E | N75W | | |
| Distance | 10 LKS | 20 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

**Original Bearing Trees Found**

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1920 By GLO

Location filed SEC. OF STATE

Monument END 12" CEDAR STUMP 6' HIGH AND BOTH BITS - NOW 10" AND 12" SET 1X36" 1/4 W/BRASS CAP 1/4 51/56 1920

(NOTES CALL FOR STAKE - BUT TREE FITS WITH BITS.)

**Bearing Trees, Reference Objects**

| | | | | |
|---|---|---|---|---|
| Species | ASH | W. OAK | | |
| Diameter | 12" | 10" | | |
| Bearing | N21 3/4E | N54W | | |
| Distance | 45 LKS | 90 LKS | | |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

**Bearing Trees, Reference Objects**

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____