


Index No. F-65

CASS COUNTY LAND CORNER RECORD

142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N.C.# 23 Corner common to sections 7B



O = Corner

EXISTING SURVEYS

Original Government Survey		Bearing Trees	
Year surveyed	<u>1874</u>	Species	<u>OAK</u> <u>Brim Gilead</u>
Original monument	<u>POST</u>	Diameter	<u>7"</u> <u>16"</u>
		Bearing	<u>N45E</u> <u>N16W</u>
		Distance	<u>45LKS</u> <u>70LKS</u>

Original Evidence Found		Original Bearing Trees Found	
Year of search	By	Species	
Monument found		Diameter	
		Bearing	
		Distance	

Subsequent Corner Restoration	
Year surveyed	<u>1926</u> By <u>GLO</u>
Location filed	<u>SEC. OF STATE</u>
Monument	<u>SET W.C. M.C. 1X36" I.P.W. / BRASS CAP</u> <u>IN MOUND OF STONE</u>

Evidence of Subsequent Corner Restoration	
Year of search	By

Bearing Trees, Reference Objects	
Year surveyed	<u>1926</u>
Species	<u>COTONWOOD</u> <u>ASIT</u>
Diameter	<u>3"</u> <u>6"</u>
Bearing	<u>N81<del>30</del>E</u> <u>N0<del>35</del>W</u>
Distance	<u>86LKS</u> <u>262LKS</u>

Bearing Trees, Reference Objects	

Subsequent Corner Restoration	
Year surveyed	By
Location filed	
Monument	

Evidence of Subsequent Corner Restoration Found	
Year of search	By

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_