| dex No CASS COUNTY LAN | D CORNER RECORD |
|--|---|
| 142 - 28 . 804 | |
| 142 R. 28 M. 57H Coordinates: X NE 17 Corner common to sections 8,9,16,17 | |
| 102 11 Corner common to sections Of 11/0/11 | |
| EXISTIN | G SURVEYS |
| Original Government Survey | Original Evidence Found |
| ear surveyed 1874 | Year of search By |
| original monument <u>Post</u> | Monument found |
| | |
| Bearing Trees | Original Bearing Trees Found O = Corner |
| Species TAM. TAM. TAM. TAM. Diameter 4" 6" 4" 4" | Species |
| Diameter 4" 6" 4" | Diameter |
| Bearing NSOE N27W 530E 520W | Bearing |
| Distance 141KS 12LKS 22 LKS 20 LKS | Distance |
| Subsequent Corner Restoration | Fuidance of Cubacassa Course Dada at the |
| 1928 C. F.L. | Evidence of Subsequent Corner Restoration |
| ear surveyed 1928 By 640 occition filed SEC. OF STATE | Year of search By |
| Mogument FNO YKY CEDAR STAKE AWN REMAINS OF ALL S | |
| BIT. S. SET RX36 "IN WIBROSS (AP T142N RZE | 4) |
| 58 59 | |
| 517 516 | |
| Bearing Trees, Reference Objects 1928 | Bearing Trees, Reference Objects |
| Species No. NEW RITS. | |
| Diameter NE NW BITS. ARE DEAD TREES, | |
| Bearing SEESW ARE REMAINS OF STUMPS | |
| Distance | Whenther |
| | |
| Subsequent Corner Restoration Year surveyed By Location filed Monument | Evidence of Subsequent Corner Restoration Found Year of search By |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | _ |
| | |
| | |
| | |
| | |
| | |
| | _ \$ |
| | <u> </u> |
| Remonumentation certificate prepared | |