


Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 22 Corner common to sections 22, 23



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1874  
 Original monument POST

**Bearing Trees**

Species	<u>CEDAR</u>	<u>TAM.</u>		
Diameter	<u>4"</u>	<u>7"</u>		
Bearing	<u>N 23 E</u>	<u>S 84 W</u>		
Distance	<u>12 LKS</u>	<u>18 LKS</u>		

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed 1919 By GLO  
 Location filed SEC OF STATE  
 Monument FIND BOTH BITS AND OLD STAKE SET 1x36" W/  
W/BASS CAP 1/4  
522/523  
1919

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>CEDAR</u>	<u>CEDAR</u>		
Diameter	<u>8"</u>	<u>6"</u>		
Bearing	<u>S 26 - 15 E</u>	<u>WEST</u>		
Distance	<u>34 LKS</u>	<u>14 LKS</u>		

**Bearing Trees, Reference Objects**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_