


Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____
N14 25 Corner common to sections 24, 25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	_____	_____
Diameter	<u>24"</u>	_____	_____
Bearing	<u>N10E</u>	_____	_____
Distance	<u>12 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E. B. HORST
Location filed COUNTY BOOK B P. 602
Monument END OLD GILT BIT (SNAG) 24" W. PINE N10E 24KS
1952, HAROLD CURE, BOOK D P. 396 END 2" BRASS
CALLED MONUMENT.

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
FND N10E BIT SET 1436" 11 P.W. BRASS CAP
1/4 524
1/4 525
1919

Bearing Trees, Reference Objects

Species	<u>POPLAR</u>	<u>SOFT MAPLE</u>	<u>MAPLE</u>	<u>MAPLE</u>
Diameter	<u>8"</u>	<u>5"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>SE</u>	<u>SW</u>	<u>N62.5BE</u>	<u>S16-53W</u>
Distance	<u>14.9'</u>	<u>12.0'</u>	<u>13.85'</u>	<u>23.35'</u>
	<u>1917 TIES</u>		<u>1952 TIES</u>	

Bearing Trees, Reference Objects

	<u>R.OAK</u>	<u>MAPLE</u>	
	<u>14"</u>	<u>6"</u>	
	<u>S8-15E</u>	<u>N71-45E</u>	
	<u>63 LKS</u>	<u>32 LKS</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - VINCENTS BOY LAKE HOMESITES
W. J. SPAIN JR 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____