


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 20 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species POPLAR POPLAR \_\_\_\_\_  
Diameter 6" 8" \_\_\_\_\_  
Bearing S70W N10E \_\_\_\_\_  
Distance 20 LKS 31 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST  
Location filed COUNTY BOOK "D" P. 7  
Monument FIND U.S.I.M.

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO  
SET 1X36" I.P. W/BRASS CAP PROPORTIONALLY  
1/4 525  
536  
1919

Bearing Trees, Reference Objects

Species OAK W. PINE \_\_\_\_\_  
Diameter 14" 8" \_\_\_\_\_  
Bearing S65-15W N15E \_\_\_\_\_  
Distance 65.4' 71.4' \_\_\_\_\_

Bearing Trees, Reference Objects

W. PINE W. OAK \_\_\_\_\_  
8" 12" \_\_\_\_\_  
N15E S66-30W \_\_\_\_\_  
109 LKS 100 LKS \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_