


Index No. V3

CASS COUNTY LAND CORNER RECORD

T. 142 R. 20 M. 5TH Coordinates: X _____ Y _____
N 14 31 Corner common to sections 30, 31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>POPULAR</u>	<u>POPULAR</u>	
Diameter <u>5"</u>	<u>6"</u>	
Bearing <u>N 25W</u>	<u>S 70W</u>	
Distance <u>8 LKS</u>	<u>16 LKS</u>	

Species	Bearing	Trees
Original Bearing Trees Found		
Species _____		
Diameter _____		
Bearing _____		
Distance _____		

Subsequent Corner Restoration

Year surveyed 1928 By GLD
Location filed SEC. OF STATE
Monument SET 1X36" I.P.W/ BRASS CAP FLUSH IN C
E-W ROAD SET 1X36" I.P.W/ BRASS CAP 1/4 S30
531
1928

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary STEVENSON
Set 2"x2"x36" STEEL post with marked
aluminum cap.

Species	Bearing	Reference Objects
<u>RIOAK</u>	<u>POPULAR</u>	
Diameter <u>6"</u>	<u>6"</u>	
Bearing <u>S 65-30E</u>	<u>S 25W</u>	
Distance <u>121 LKS</u>	<u>66 LKS</u>	

Species	Bearing	Reference Objects
<u>OAK</u>	<u>OAK</u>	
Diameter <u>10"</u>	<u>14"</u>	
Bearing <u>S 40W</u>	<u>S 35E</u>	
Distance <u>80.47'</u>	<u>74.44'</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1988 Certificate - Gary STEVENSON
Doc. # 304199
Sept. 2003 M. Landecker # 7452
Gen of Surv. shows Mon. Found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____